




Reconditioning Service

Non-Restorable Examples: Items Beyond Reconditioning

Welcome to our guide highlighting examples of Lindström precision cutters that are deemed unsuitable for reconditioning. While the process of refurbishment and restoration holds promise for many objects, there are instances where damage or degradation surpasses the point of feasible repair. In this document, we present a curated collection of such items, illustrating the various conditions that render them irreparable or beyond restoration.

Please note that tools will be automatically rejected if they have

 Broken Tips



 Excessive divots in the cutting blades



 Broken metal handles



 Broken joints

